


RECREATION GROUND

Date: 14 May 2024 Barbara

	Condition. Good/ Satisfactory/ Poor	Action required	Immediate action required? Yes/No	Action completed to satisfaction. Yes/No	Photo before/after
Site General (to include surfaces and paths)	G	Dead branch in HC tree	yes		
Sign	G				
Gate	G				
EV charging point	G				
Bench (with back)	G				
Litter Bin - at pavilion	G				
Litter Bin - car park	G				
Climbing Frame	G				
Free Standing Slide	G				
Swing (2 seat, flat)	G				
Swing (2 seat, cradle)	G				

